



**Waste Discharge Requirements For
Chevron USA, Inc.
Section 29 Surface Impoundments, Lost Hills Oil Field
Kern County**

Order Number R5-2005-_____

VICINITY MAP

Section 29, T26S, R21E, MDB&M
Lost Hills NW 7.5 Minute USGS Quadrangle

- ? Boring locations
- ⊠ Monitoring well
- ? Munger Farms well
- ? Stock watering well
- Cross-section line (Attachment C)

N
↑
1" = 2000'

Attachment B